



RETAIL FOOD FACILITY INSPECTION REPORT

DBA: Jack in the Box

Address: Sharp City: _____

Re-inspection

OBSERVATIONS AND CORRECTIVE ACTIONS

Air temperature at cook line 88°F - 91°F; air from vents at cook line 89°F - 94°F.

Manager reports air conditioning unit serviced this morning but denning area vents returning air at 71°F - 72°F.

Repair cook line unit to provide a reasonable level of comfort for cook line workers.

Re-inspection to follow in 4+ days. Re-inspection fees apply to subsequent inspections.

If unable to properly repair unit in timely fashion, recommend venting or buying portable air conditioner for cook line.

Owner/Operator Init: [Signature]

REHS Init: [Signature]